

Intermec's FlexDock System

A uniquely scalable and modular docking system giving users the flexibility to design the docking system that best suites their needs today, as well as in the future.

Accessories Guide

CONTENTS

Design Your Own:

| | |
|---|---|
| Bases | 1 |
| Desktop Modules..... | 2 |
| Power Supplies | 2 |
| AC Line Cords | 2 |
| Mobile Computer Cups | 3 |
| Mobile Printer Cups | 3 |
| Mobile Computers and Printers Battery Cups | 4 |
| Covers..... | 4 |
| Mounting Kits..... | 4 |

Common Mixed Configurations

Pre-Configured:









| | |
|--|----|
| CN70 & CN70e FlexDocks..... | 6 |
| CN3, CN3e, CN4 & CN4e FlexDocks | 7 |
| CN50 FlexDocks..... | 7 |
| CS40 FlexDocks..... | 8 |
| CK70 & CK71 FlexDocks..... | 9 |
| CK3 FlexDocks | 10 |
| Mobile Receipt Printers FlexDocks | 10 |



Design Your Own:

Choose your Base and add the appropriate Cups, Power Supply and Line Cord.

Bases

| Accessory Name | Part Number | Description |
|--|-------------|--|
| Quad Charge Only  | 852-916-001 | Provides 4 bays for charging individual devices and/or battery packs. Power supplies and country specific line cords must be ordered separately. |
| Quad Ethernet   Back View | 852-917-001 | Provides 4 bays for Ethernet communications and charging individual devices and/or battery packs. Power supplies and country specific line cords must be ordered separately. |
| Dual Charge Only  | 852-918-001 | Provides 2 bays for charging individual devices and/or battery packs. Power supplies and country specific line cords must be ordered separately. |
| Dual Ethernet   Back View | 852-919-001 | Provides 2 bays for Ethernet communications and charging individual devices and/or battery packs. Power supplies and country specific line cords must be ordered separately. |
| Desktop  Assembled Desktop Dock  <div> Bay 2: Dedicated Battery Cup Bay 1: Computer Cup </div> | 852-920-001 | Provides (2) bays with dedicated functionality. Bay 1: Accommodates mobile device for charging and Ethernet or modem or USB host communications, as well as USB client connectivity. Ethernet and modem communications require add-on modules listed below. Bay 2: Used for charging up to (2) batteries. Power supplies and country specific line cords must be ordered separately. |

Intermec's FlexDock System

Accessory Guide

Desktop Modules

| Accessory Name | Part Number | Description |
|------------------------------|-------------|--|
| Desktop Dock Ethernet Module | 871-238-001 | Module plugs into USB port of Desktop base to provide Ethernet communications. |



Desktop Dock
w/ Ethernet
Module



Ethernet Module

| | | |
|---------------------------|-------------|---|
| Desktop Dock Modem Module | 871-238-002 | Module plugs into USB port of Desktop base to provide modem communications. |
|---------------------------|-------------|---|

Power Supplies

| Accessory Name | Part Number | Description |
|--------------------------|-------------|--|
| Quad Base Power Supplies | 851-064-317 | A 100W power supply for use with Quad Charge Only and Quad Ethernet Bases. Requires country specific line cord to be ordered separately. |



| | | |
|-----------------------------------|--------------------------------------|---|
| Dual or Desktop Base Power Supply | 851-095-021 851-095-121 (EU only) | A 48W power supply for use with Dual Charge Only, Dual Ethernet, and Desktop Bases. Requires country specific line cord to be ordered separately. |
|-----------------------------------|--------------------------------------|---|



AC Line Cords

| | |
|-----------------------------|--------------|
| Power Cord - China | 071918 |
| Power Cord - Europe | 1-974027-025 |
| Power Cord - UK | 1-974029-020 |
| Power Cord - Australia | 1-974030-025 |
| Power Cord - Italy | 321-471-002 |
| Power Cord - Japan | 321-500-002 |
| Power Cord - Denmark | 321-501-002 |
| Power Cord - India/S Africa | 321-502-002 |
| Power Cord - US | 1-074028-025 |
| Power Cord - Switzerland | 321-470-001 |


Intermec's FlexDock System

Accessory Guide

Mobile Computer Cups

| Accessory Name | Part Number | Description |
|--|-------------|--|
| CK3 Mobile Computer Cup  | 203-916-001 | Supports (1) mobile computer when snapped into a bay of base unit. |
| CK70/71 Mobile Computer Cup  | 203-921-001 | Supports (1) mobile computer when snapped into a bay of base unit. |
| CN3(e)/CN4(e) Mobile Computer Cup  | 203-914-001 | Supports (1) mobile computer when snapped into a bay of base unit. |
| CN50 Mobile Computer Cup  | 203-918-001 | Supports (1) mobile computer when snapped into a bay of base unit. |
| CN70/70e Mobile Computer Cup  | 203-920-001 | Supports (1) mobile computer when snapped into a bay of base unit. |
| CS40 Mobile Computer Cup  | 203-923-001 | Supports (1) mobile computer when snapped into a bay of base unit. |





Mobile Printer Cups

| Accessory Name | Part Number | Description |
|---|-------------|--|
| PR2/PR3 Mobile Receipt Printer Cup  | 203-964-001 | Support (1) mobile printer when snapped into a bay of base unit. |

Intermec's FlexDock System

Accessory Guide

Mobile Computers and Printers Battery Cups

| Accessory Name | Part Number | Description |
|--|-------------|--|
| CK70/71 & CK3 Battery Cup | 203-917-001 | Supports charging of (2) batteries when snapped into a bay of base unit. |
|  | | |
| CN70/70e Battery Cup | 203-922-001 | Supports charging of (2) batteries when snapped into a bay of base unit. |
|  | | |
| CS40 Battery Cup | 203-924-001 | Supports charging of (2) batteries when snapped into a bay of base unit. |
|  | | |
| PR2/PR3 Mobile Receipt Printer Battery Cup | 203-965-001 | Supports charging of (2) batteries when snapped into a bay of base unit. |
|  | | |

Covers

| Accessory Name | Part Number | Description |
|----------------|-------------|--|
| Blank Cover | 203-926-001 | Optional cover for base bays currently not in use. Intended to prevent debris from accumulating on exposed bay contacts. |




Mounting Kits

| Accessory Name | Part Number | Description |
|-------------------|-------------|---|
| Wall Mounting Kit | 203-641-002 | Consists of (1) metal rack with pre-drilled holes for securing FlexDock bases and mounting to wall surface. Also used with 700 Series, CK61, and CN3 / CN4 Series. |
| Rack Mounting Kit | 203-945-001 | Consists of (1) metal rack with pre-drilled holes for securing FlexDock bases and for mounting vertically to uprights of standard 19" (48 cm) IT equipment rack. Includes thumbscrews and two adapters for mounting racks upto 15 degree angle for better viewability. (Standard IT rack must be ordered separately.) |

Intermec's FlexDock System

Accessory Guide

Common Mixed Configurations

| Accessory Name | Part Numbers | Description |
|--|--|--|
| CN50/PR2 Dual Charge  | 852-918-001 203-918-001 203-964-002 851-095-021/121 | Supports charging (1) CN50 computer and (1) PR2 or PR3 receipt printer. Country specific line cords must be ordered separately. |
| CN70/PR2 Dual Charge  | 852-918-001 203-920-001 203-964-002 851-095-021/121 | Supports charging (1) CN70 or CN70e computer and (1) PR2 or PR3 receipt printer. Country specific line cords must be ordered separately. |
| PR2/3 Battery and Printer Quad Charge  | 852-916-001 203-964-001 x 2 203-965-001 x 2 851-095-021/121 | Support charging (4) PR2/3 battery packs and (2) PR2 or PR3 printers. Country specific line cords must be ordered separately. |










For additional options, see the "Design Your Own" Section.

Intermec's FlexDock System

Accessory Guide

*Pre-Configured:
Ready to Go out of the box.*

CN70 & CN70e FlexDocks

| Accessory Name | Part Number | Description |
|--|---|---|
| CN70/70e Quad Charge Only  | DX4A2111100 DX4A2111110 (incl NA cord) | Supports charging for up to (4) CN70 and/or CN70e computers. Includes power supply. Country specific line cords must be ordered separately. |
| CN70/70e Quad Ethernet   | DX4A1111100 DX4A1111110 (incl NA cord) | Supports Ethernet communications and charging for up to (4) CN70 and/or CN70e computers. Includes power supply. Country specific line cords must be ordered separately. |
| CN70/70e Dual Charge Only  | DX2A21100 DX2A21110 (incl NA cord) | Supports charging for up to (2) CN70 and/or CN70e computers. Includes power supply. Country specific line cords must be ordered separately. |
| CN70/70e Dual Ethernet   | DX2A11120 DX2A11110 (incl NA cord) | Supports Ethernet communications and charging for up to (2) CN70 and/or CN70e computers. Includes power supply. Country specific line cords must be ordered separately. |
| CN70/70e Desktop  | DX1A01A00 DX1A01A10 (incl NA cord) | Supports (1) CN70 or CN70e computer for charging and Ethernet or modem or USB host communications, as well as USB client connectivity; and battery charging for up to (2) CN70/e batteries. Ethernet and modem communications require add-on modules listed under "Design Your Own" section. Includes power supply. Country specific line cords must be ordered separately. |
| CN70/70e 4-Position Battery Charger  | DX2A2AA00 DX2A2AA10 (incl NA cord) | Supports charging for up to (4) CN70 or CN70e batteries. Includes power supply. Country specific line cords must be ordered separately. |
| CN70/70e 8-Position Battery Charger  | DX4A2AAAA00 DX4A2AAAA10 (incl NA cord) | Supports charging for up to (8) CN70 or CN70e batteries. Includes power supply. Country specific line cords must be ordered separately. |

Intermec's FlexDock System

Accessory Guide

CN3, CN3e, CN4 & CN4e FlexDocks

| Accessory Name | Part Number | Description |
|--------------------------|---|--|
| CN3/CN4 Quad Charge Only | DX4A2333300 DX4A2333310 (incl NA cord) | Supports charging for up to (4) CN3/e and/or CN4/e computers. Includes power supply. Country specific line cords must be ordered separately. |
| CN3/CN4 Quad Ethernet | DX4A1333300 DX4A1333310 (incl NA cord) | Supports Ethernet communications and charging for up to (4) CN3/e and/or CN4/e computers. Includes power supply. Country specific line cords must be ordered separately. |



Back View

CN50 FlexDocks

| Accessory Name | Part Number | Description |
|-----------------------|---|--|
| CN50 Quad Charge Only | DX4A2555500 DX4A2555510 (incl NA cord) | Supports charging for up to (4) CN50 computers. Includes power supply. Country specific line cords must be ordered separately. |
| CN50 Quad Ethernet | DX4A1555500 DX4A1555510 (incl NA cord) | Supports Ethernet communications and charging for up to (4) CN50 computers. Includes power supply. Country specific line cords must be ordered separately. |












Back View

Intermec's FlexDock System

Accessory Guide










CS40 FlexDocks

| Accessory Name | Part Number | Description |
|---|--|--|
|  | DX4A2666600 DX4A2666610 (incls NA cord) | Supports charging for up to (4) CS40 computers. Includes power supply. Country specific line cords must be ordered separately. |
|   Back View | DX4A1666600 DX4A1666610 (incls NA cord) | Supports Ethernet communications and charging for up to (4) CS40 computers. Includes power supply. Country specific line cords must be ordered separately. |
|  | DX2A26600 DX2A26610 (incls NA cord) | Supports charging for up to (2) CS40 computers. Includes power supply. Country specific line cords must be ordered separately. |
|   Back View | DX2A16600 DX2A16610 (incls NA cord) | Supports Ethernet communications and charging for up to (2) CS40 computers. Includes power supply. Country specific line cords must be ordered separately. |
|  | DX1A06E00 DX1A06E10 (incls NA cord) | Supports (1) CS40 computer for charging and Ethernet or modem or USB host communications, as well as USB client connectivity; and battery charging for up to (2) CS40 batteries. Ethernet and modem communications require add-on modules listed under "Design Your Own" section. Includes power supply. Country specific line cords must be ordered separately. |
|  | DX2A2EE00 DX2A2EE10 (incls NA cord) | Supports charging for up to (4) CS40 batteries. Includes power supply. Country specific line cords must be ordered separately. |
|  | DX4A2EEEE00 DX4A2EEEE10 (incls NA cord) | Supports charging for up to (8) CS40 batteries. Includes power supply. Country specific line cords must be ordered separately. |

Intermec's FlexDock System

Accessory Guide






CK70 & CK71 FlexDocks

| Accessory Name | Part Number | Description |
|---|---|---|
|  | DX4A222200 DX4A222210 (incl NA cord) | Supports charging for up to (4) CK70 and/or CK71 computers. Includes power supply. Country specific line cords must be ordered separately. |
|   Back View | DX4A122200 DX4A122210 (incl NA cord) | Supports Ethernet communications and charging for up to (4) CK70 and/or CK71 computers. Includes power supply. Country specific line cords must be ordered separately. |
|  | DX2A22200 DX2A22210 (incl NA cord) | Supports charging for up to (2) CK70 and/or CK71 computers. Includes power supply. Country specific line cords must be ordered separately. |
|   Back View | DX2A12200 DX2A12210 (incl NA cord) | Supports Ethernet communications and charging for up to (2) CK70 and/or CK71 computers. Includes power supply. Country specific line cords must be ordered separately. |
|  | DX1A02B00 DX1A02B10 (incl NA cord) | Supports (1) CK70 or CK71 computer for charging and Ethernet or modem or USB host communications, as well as USB client connectivity; and battery charging for up to (2) CK70, CK71 or CK3 batteries. Ethernet and modem communications require add-on modules listed under "Design Your Own" section. Includes power supply. Country specific line cords must be ordered separately. |
|  | DX2A2BB00 DX2A2BB10 (incl NA cord) | Supports charging for up to (4) CK7x or CK3 batteries. Includes power supply. Country specific line cords must be ordered separately. |
|  | DX4A2BBBB00 DX4A2BBBB10 (incl NA cord) | Supports charging for up to (8) CK7x or CK3 batteries. Includes power supply. Country specific line cords must be ordered separately. |





Intermec's FlexDock System

Accessory Guide

CK3 FlexDocks

| Accessory Name | Part Number | Description |
|--|---|---|
| CK3 Quad Charge Only  | DX4A2444400 DX4A2444410 (incl NA cord) | Supports charging for up to (4) CK3 computers. Includes power supply. Country specific line cords must be ordered separately. |
| CK3 Quad Ethernet   Back View | DX4A1444400 DX4A1444410 (incl NA cord) | Supports Ethernet communications and charging for up to (4) CK3 computers. Includes power supply. Country specific line cords must be ordered separately. |
| CK3 4-Position Battery Charger  | DX2A2BB00 DX2A2BB10 (incl NA cord) | Supports charging for up to (4) CK3 and/or CK7x batteries. Includes power supply. Country specific line cords must be ordered separately. |
| CK3 8-Position Battery Charger  | DX4A2BBBB00 DX4A2BBBB10 (incl NA cord) | Supports charging for up to (8) CK3 and/or CK7x batteries. Includes power supply. Country specific line cords must be ordered separately. |

Mobile Receipt Printers FlexDocks

| Accessory Name | Part Number | Description |
|---|--|---|
| PR2/3 Quad Charge Only  | DX4A2777700 (Global) DX4A2777710 (incl NA cord) | Supports charging for up to (4) PR2 or PR3 receipt printers. Includes power supply. Country specific line cords must be ordered separately. |
| PR2/3 Dual Charge Only  | DX2A27700 (non EU) DX2A27710 (incl NA cord) DX2A27720 (Global) | Supports charging for up to (2) PR2 or PR3 receipt printers. Includes power supply. Country specific line cords must be ordered separately. |
| PR2/3 4-Position Battery Charger  | DX2A2FF00 (non EU) DX2A2FF10 (incl NA cord) DX2A2FF20 (Global) | Supports charging for up to (4) PR2 or PR3 batteries. Includes power supply. Country specific line cords must be ordered separately. |
| PR2/3 8-Position Battery Charger  | DX4A2FFFF00 (Global) DX4A2FFFF10 (incl NA cord) | Supports charging for up to (8) PR2 or PR3 batteries. Includes power supply. Country specific line cords must be ordered separately. |



Copyright © 2012 Intermec Technologies Corporation. All rights reserved. Intermec is a registered trademark of Intermec Technologies Corporation. All other trademarks are the property of their respective owners.
612150-01A 04/12